



C.H.J. Incorporated

Hesperia Water Tank Site Plant 19a

Client: City of Hesperia



CHJ performed the investigations, materials testing and special inspection services for two of the three water tanks at Plant 19a in Hesperia. CHJ was also responsible for the entire site as the Owner's On-site Construction Coordinator. Our ICBO certified special inspectors inspected and sampled all construction materials involved in this project including bolting inspection, reinforced steel welding inspection, monitored slump and concrete placement, mixed design identification, and plan review. We also provided the paint and coating inspections needed for these tanks with our certified NACE inspector. ○



People you can depend on, Experience you can trust, "Service to Our Clients"