



**C.H.J.** Incorporated

## Storage Facility Phase I, II, III

*Client: Grady Trust*



**CHJ performed Phase I, Phase II, and Phase III Environmental Site Assessments** on 1160 Airport Drive at the request of the Grady Trust. As a result of the investigation, evidence of contamination of on-site and off-site soils due to the actions of a former site tenant was found. Copper and Lead were found in the nearby soil and were excavated to remove most of the chemicals that had leaked into these soils.



*People you can depend on, Experience you can trust, "Service to Our Clients"*